

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

Amendments to the Claims:

This listing of claims will replace all prior versions, and listings, of claims in the application:

Listing of Claims:

Claim 1 (currently amended): A locking configuration, comprising:

an adjustable steering column;

a fixed mounting;

a tilt-adjustable casing tube secured on said fixed mounting, said tilt-adjustable casing tube surrounding said adjustable steering column;

a locking device provided between said fixed mounting and said tilt-adjustable casing tube, said locking device having an actuating lever pivotable between a locking position and a release position such that said actuating lever pivots laterally next to or below said tilt-adjustable casing tube and such that the ~~releases~~ release position is below the locking position;

BEST AVAILABLE COPY

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

said locking device having a handle component for said actuating lever, said handle component being disposed at a given distance from said tilt-adjustable casing tube when said actuating lever is in the locking position; and

said actuating lever having an angled region formed with a predetermined buckling point and being configured as a deformation element for absorbing energy wherein said actuating lever is deformable in a crash such that said handle component moves toward said tilt-adjustable casing tube.

Claim 2 (canceled)

Claim 3 (currently amended): The locking configuration according to claim 1, wherein said ~~actuating lever has~~ angled region is a hook-shaped bent region adjacent said handle component ~~and is formed with a predetermined buckling point at said hook shaped bent region.~~

Claim 4 (currently amended): The locking configuration according to claim 1, wherein:

said actuating lever has a cross-sectional profile selected from the group consisting of a rectangular profile and a T-shaped profile; and

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

~~said actuating lever has a given region selected from the~~
~~group consisting of an angled region and a bent region, said~~
~~given~~ said angled region having a reduction in cross section
for forming a predetermined buckling point.

Claim 5 (original): The locking configuration according to
claim 1, wherein:

said actuating lever is formed of metal; and

said handle component has a metal core with a plastic coating
and is screwed to said actuating lever.

Claim 6 (original): The locking configuration according to
claim 1, wherein:

said actuating lever is formed of steel;

said handle component has a metal core with a plastic coating;
and

said actuating lever and said handle component are connected
to one another as a two-part element.

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

Claim 7 (original): The locking configuration according to claim 1, including:

~~a steering-column cladding surrounding said locking device and~~
said tilt-adjustable casing tube;

said steering-column cladding having a receiving trough formed therein for accommodating said handle component; and

said receiving trough extending in a direction toward said tilt-adjustable casing tube and having a recess formed therein for providing a pass-through for said actuating lever.

Claim 8 (original): The locking configuration according to claim 7, wherein said steering-column cladding is configured as a deformation element for absorbing impact energy.

Claim 9 (original): The locking configuration according to claim 7, wherein:

said handle component has a side facing away from said steering column; and

said side of said handle component facing away from said steering column is disposed substantially flush with said

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

steering-column cladding when said actuating lever is in the locking position.

~~Claim 10 (original): The locking configuration according to~~
claim 7, including deformation elements provided between said tilt-adjustable casing tube and said steering-column cladding.

Claim 11 (currently amended): In combination with a vehicle having an adjustable steering column, a fixed mounting and a tilt-adjustable casing tube secured on the fixed mounting and surrounding the adjustable steering column, a locking device, comprising:

an actuating lever pivotable between a locking position and a release position such that said actuating lever pivots laterally next to or below the tilt-adjustable casing tube and such that the ~~releases~~ release position is below the locking position;

a handle component connected to said actuating lever, said handle component being disposed at a given distance from the tilt-adjustable casing tube when said actuating lever is in the locking position; and

Applic. No. 10/782,324
Response Dated April 25, 2005
Responsive to Office Action of March 25, 2005

said actuating lever having an angled region formed with a

predetermined buckling point and being configured as a

~~deformation element for absorbing energy wherein said~~

~~actuating lever is deformable in a crash such that said handle~~

component moves toward the tilt-adjustable casing tube.

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ **BLACK BORDERS**

☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**

☐ **FADED TEXT OR DRAWING**

☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**

☐ **SKEWED/SLANTED IMAGES**

☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**

☐ **GRAY SCALE DOCUMENTS**

☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**

☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**

☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.